## Standard Operating Procedure for Radiation Safety/Radiation Safety Officer Duties

1.0 Location

**Room 306** 

2.0 Purpose

To Inform and protect personnel working in this area.

3.0 Reference

Current North Dakota Radiological Health Rules

- 4.0 Procedures
  - 4.1 Radiation Safety Procedures
    - 4.1.1 A radioactive material inventory must be done every 6 months, and documented in the Radioactive Materials Logbook.
    - 4.1.2 Leak tests are required on the Nickel 63 sources in the gas chromatographs every 6 months, and documentation is kept in the Radioactive Materials License
    - 4.1.3 Contamination Control
      - 4.1.3.1 Do not mouth pipette radioactive materials.
      - 4.1.3.2 Do not eat, drink, smoke, or apply cosmetics where radioactive materials are used.
      - 4.1.3.3 All radiological work should be done in a designated, posted laboratory area.
      - 4.1.3.4 Use protective gloves and lab coats when handling radioactive materials
      - 4.1.3.5 Thoroughly wash hands after handling radioactive materials.
    - 4.1.4 Radioactive Spills Cleanup

- 4.1.4.1 Spills should be quickly wiped up and the contaminated cleaning materials placed in radioactive waste. Cleanup should be performed while wearing disposable protective covering prior to testing.
- 4.1.4.2 For containment, place absorbent material around the edges of the spill.
- 4.1.4.3 Blot up as much of the spilled material as possible, placing soaked materials in a waste bag.
- 4.1.4.4 Wash the area with dilute Contrad 70 solution. Wipe a small portion of the area with a dry filter paper and count by liquid scintillation.
- 4.4.4.5 The amount of removable activity should be less then twice background.
- 4.2 Duties of the Radiation Safety Officer
  - 4.2.1 Maintain license and all records.
  - 4.2.2 Order all radioactive materials.
  - 4.2.3 Inventory and leak test radioactive material every 6 months.
  - 4.2.4 Train new employees.
  - 4.2.5 Keep log and records of safety training.
  - 4.2.6 Perform counting and reporting of leak/wipe tests.
  - 4.2.7 Supervise to ensure that licensed material is properly secured against unauthorized removal at all times.
  - 4.2.8 Development of operating and emergency procedures.
  - 4.2.9 Provide advice and help for accidents and emergencies.
  - 4.2.10 Maintain supplies, such as radiation safety supplies, radiation signs, tapes, and labels.

SOP I-3-10 Rev. 11-05-03 Page 3 of 3

4.2.11 Conduct annual review to ensure compliance with the rules and license conditions.